

Technical Report:	
Date Received:	

(9619) 183-0219 JULY 02, 2019 JULY 31, 2019 Page 1 of 4

CONG TY TNHH SON HOA VIET TDS34, TBD23, LONG BINH, KHANH BINH, TAN UYEN, BINH DUONG

Sample Description:	SON SAN MAU TRANG		
Vendor:	CONG TY TNHH SON HOA	Sample Size:	/
	VIET		
Manufacturer:	SON HOA VIET	VPN:	/
Buyer:	/	SKN/SKU No.:	/
Agent:	/		
Labeled Age Grade:	/	PO No.:	/
Appropriate Age Grade:	/	Ref #:	/
Client Specified Age Grade:	/	Country of Origin:	VIETNAM
Tested Age Grade:	/	Assortment No.:	/
UPC Code:	/	Department No.:	/
Phase of Production:	/	ITEM#:	/
Color:	/	Date of Production:	/
Program:	/	Model/Style#:	/
Previous No:	N/A	Country of Destination:	/

TEST:

EN ISO 105 B02 Colorfastness To Light

EXECUTIVE SUMMARY:

The sample(s) was tested to the following requirement(s) and the data provided is for informational purposes only:

- The requirements of EN ISO 105 B02, colorfastness to light (500 hours).

Note(s):

- This report includes the test result(s) which was conducted & reviewed by Softline department.

This report is governed by, and incorporates by reference, CPS Conditions of Service as posted at the date of issuance of this report at http://www.bureauveritas.com/home/about-us/our-business/cps/about-us/terms-conditions/and is intended for your exclusive use. Any copying or replication of this report at or for any other person or entity, or use of our name or trademark, is permitted only with our prior written permission. This report sets forth our findings solely with respect to the test samples identified herein. The results set forth in this report are not indicative or representative of the quality or characteristics of the lot from which a test sample was taken or any similar or identical product unless specifically and expressly noted. Our report includes all of the tests requested by you and the results thereol based upon the information that you provided to us. Measurement uncertainty is only provided upon request for accredited tests. You have 60 days from date of issuance of this report to notify us of any material error or mission caused by our negligence or if you require measurement uncertainty; or uses the issue you wish to raise. A failure to raise such issue within the prescribed time shall constitute you unqualified acceptance of the completeness of this report, the tests conducted and the correctness of the report contents.



CONG TY TNHH SON HOA VIET Technical Report: **(9619) 183-0219** JULY 31, 2019 Page 2 of 4

If there is any question regarding this report, please contact the following lab personnel:

Administrative inquiries, please contact:

Primary Contact: Elise Vo, Tel: 84-028-37421-604 ~ 6, Ext: 394; email: elise.vo@vn.bureauveritas.com Back-up Contact: Angelina Hong, Tel: 84-028-37421-604 ~ 6, Ext: 868; email: angelina.hong@vn.bureauveritas.com

Technical inquiries, please contact:

Primary Contact: Terry Nguyen, Tel: 84-028-37421-604 ~ 6, Ext: 355; email: terry.nguyen@vn.bureauveritas.com Back-up Contact: Ron Nguyen, Tel: 84-028-37421-604 ~ 6, Ext: 313; email: ron.nguyen@vn.bureauveritas.com

BUREAU VERITAS CONSUMER PRODUCTS SERVICES (VN) LTD.

hu

TERRY NGUYEN AUTHORIZED REPORT APPROVER – HARDLINE, TOYS & JUVENILE PRODUCTS DIVISION



CONG TY TNHH SON HOA VIET Technical Report: **(9619) 183-0219** JULY 31, 2019 Page 3 of 4

RESULT(S):

Evaluation	Citation / Method	No. of Samples	Criteria	Results	Rating
Colorfastness To Light	BS EN ISO 105 B02	-	Report as DATA at 500 Hours	Color Change: Grade 4.5	DATA

Results Key:

М	Meets	NM	Does Not Meet
NA	Not Applicable	NT	Not Tested
С	Claimed	R	Recorded

RATING COLOR CHANGE

- 5 negligible or no change or staining

- 4 slightly changed or stained
 3 noticeably changed or stained
 2 considerably changed or stained
- 1 heavily changed or heavily stained



CONG TY TNHH SON HOA VIET Technical Report: **(9619) 183-0219** JULY 31, 2019 Page 4 of 4

